
Pathos

SMALL TABLES

Antonio Citterio



Description

The top is square with rounded corners and refined details on the curved edges and is available in Marquinia black marble, Calacatta white marble, Guatemala green marble, Sahara noir marble or in MDF wood fibre painted in the glossy colours: desert, anthracite, steel grey, marsh brown or brick red. The frame is in bright chromed, bronzed nickel painted, satin brass or with copper finish steel.

Technical information

Top:

MDF wood fibre panel

Top finish:

glossy painted: anthracite, desert, steel grey, marsh brown or brick red

Top finish (SMTO5P):

Calacatta white marble (glossy polyester finish), Marquinia black marble (glossy polyester finish), Guatemala green marble (glossy polyester finish) or Sahara noir marble (glossy polyester finish)

Top finish (SMTV11P-SMTV14P):

Calacatta white marble (glossy polyester finish), Marquinia black marble (glossy polyester finish) or Guatemala green marble (glossy polyester finish)

Support frame:

bright chromed, bronzed nickel painted, with brass finish or with copper finish drawn steel

Support frame (SMT4L-SMTO8L):

bright chromed, black chromed, bronzed nickel painted, with brass finish or with copper finish drawn steel


Support frame (SMTO5P-SMTV11P-SMTV14P):

bright chromed, with brass finish or with copper finish drawn steel


Ferrules:

plastic material


Technical drawings




SMT4L




SMT05L




SMT05P




SMT08L




SMTV11




SMTV11P




SMTV14



SMTV14P



SMTB15



SMTB19

B&B Italia reserves the right to make technological and aesthetic improvements to its models, including changes to the sizes and materials, without notice. The technical drawings do not define the details of the product. The measurements shown are indicative and may undergo changes. In particular, the dimensions relevant to the padded parts are subject to usage tolerances over time caused by the normal adjustment of the padding. For the specific information, please contact the dealer closest to you.